Next 1 Page(s) In Document Exempt

Approved For Relaise 20

05439A000200390117-2

25X1C

MAC & 1872 K

MOTOBRAPHIC WITERPRETATION SEE

HALIM PERDANAKUSUMA AIRFIELD.
INDONESIA

5-9762

3

Declassification review by NIMA/DoD

25X1C

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER		PHOTO INTERPRETATION BRIEF	
Title: Halim Perdanakusuma Airfield, Indonesia	Geo Coords: 06-15S 106-54E NPIC Target No: 0982-1	Publication No: NPIC/R-1492/63 2: Date: September 1963	5X1A

25X1C Photo Data

25X1D

25X1D

25X1D

References: AMS Series T503, Sheet SB 48-12, 1st ed, May 58 (U); AMS Series T725 Sheet 4324 11, 1st ed, Oct 60 (U). NPIC Project J-315/63

Halim Perdanakusuma Airfield, a major AURI base situated 6 nm SE of the center of Djakarta and 0.7 nm west of Pangkalan, comprises the airfield and a SAM holding area.


The airfield has an approximately 8,000 x 200 ft ENE/WSW probably asphalt, serviceable runway. In an erosion ditch was observed across the runway approximately 700 ft from the WSW end. Photography of 1/ showed the runway in a late stage of

repair with construction equipment evident.

Facilities include 3 large and one mediumsized hangar with concrete aprons at each end, a control tower, numerous barracks and support buildings, a parallel taxiway, and 2 approximately 4,400 x 190 ft NNW/SSE taxiways with a total of 24 hardstands.

Aircraft observed on include 4 Farmer, 2 Fresco, 2 Fagot, 8 C-130, 12 Crate, 6 Cab, one Colt, one B-25, 5 T-6,

ⁱⁿ⁻ 25X1D



- 1 - 25X1D

SECRET

25X1C

10 T-34-A, and 2 small, single-engine, straightwing aircraft.

25X1D Aircraft observed on include one Farmer, 2 Fresco, 2 Fagot, 6 C-130, 9 Crate, 7 Cab, one Colt, one B-25, one Hound, and 12 small, single-engine, straight-wing aircraft.

The SAM holding area, situated immediately south of the airfield, contains 2 radar pads (one with a Token-type radar and 2 vans and the other unoccupied), a loop road with

18 SA-2 missile launchers, 5 vans, 3 possible vans, and 15 unidentified objects in one of 6 revetted hardstands. Four quonset huts, 4 probable storage buildings, and approximately 6 associated buildings were observed in the holding area. Photography of revealed no change in the amount of equipment.

25X1D

ADDITIONAL REFERENCE

25X1D